





Medium Frequency (Left)			
	Treat-time(min)	Power(%) - PWM(%)	State
1	20	15 - 15	Run
2	20	15 - 15	Run
3	20	15 - 15	Run
4	20	15 - 15	Run
5	20	15 - 15	Run
6	20	15 - 15	Run

Medium Frequency (Right)			
	Treat-time(min)	Power(%) - PWM(%)	State
1	20	15 - 15	Run
2	20	15 - 15	Run
3	20	15 - 15	Run
4	20	15 - 15	Run
5	20	15 - 15	Run
6	20	15 - 15	Run

US Power (Left)

1 2 3 4 5 6

Treat Time 20 M
Work(sec) 1 S
Rest(sec) 1 S

US Power (Right)

1 2 3 4 5 6

Treat Time 20 M
Work(sec) 1 S
Rest(sec) 1 S

- Start(L)
- Pause(L)
- Treat. Info.
- Previous
- Move Main
- Pause(R)
- Start(R)

Channel-L: Status

Channel-R: Status